

Town of Laurel Park - Helene Repairs

List of Projects - Updated 10/16/25

DI	Name	Road	Description
Culvert Replacements (Project Number 803265)			
1414120 C	NCLP-DM#1C	Davis Mountain Road	Culvert at intersection of Davis Mountain Road and Old Orchard Drive has partially washed out. The culvert will have to be replaced and the road repaired.
1414122 C	NCLP-WL#1C	Woodbyne Lane	Culvert washout with impact to the road at the intersection of Woodbyne Lane and Sliver Springs Drive. Culvert will have to be replaced and road repaired.
1414124 C	NCLP-PD#1C	Panorama Drive	Culvert washout with impact to the road. Culvert will have to be replaced and road repaired.
1414126 C	NCLP-RD#1C	Ransier Drive	Culvert and roadway completed washed out. Culvert will have to be replaced and road repaired.
1414137 C	NCLP-LD#1C	Lake Drive	Culvert washout with sink hole and damage to roadway.
1414123 C	NCLP-WL#2C	Woodbyne Lane	Culvert is blocked with mud and other storm debris. Area will need to be cleaned up and culvert assessed for replacement.
1414138 C	NCLP-SS#1C	Silver Springs Drive	Culvert was partially washed out during the storm. Wash out area will have to be backfilled with stone and road repaired.
1414125 C	NCLP-PD#2C	Panorama Drive	Culvert partially washed out with minor impact to the road.
1414140 C	NCLP-SD#1C	Skyway Drive	Culvert damaged and sink hole beginning to form. Culvert will have to be replaced.
1504369 C	NCLP-BC#1C	Beechwood Circle	Culvert partially washed out with damage to the shoulder. Culvert will likely have to be replaced
1509859 C	NCLP-WT#1C	Woodland Trail	Pavement has settled at a sinkhole around an existing inlet. Storm drainage inlet and pavement will have to be repaired.
1414136 C	NCLP-BD#1C	Briarcliff Drive	Culvert washout with damage to roadway.
1504369 C	NCLP-BC#1S	Beechwood Circle	Multiple slide areas on the upper side of Laurel Park Highway that has impact drainage swales and culverts. Material must be removed from ditches, shoulder and roadway.
Project - Hebron Road Area (Project Number 767028) - NCDOT Project (Federal Aid Route)			
1414101 C	NCLP-HR#2S	Hebron Road	Major slide on lower side of the road with impacts to the roadway and stream below.
1414102 C	NCLP-HR#3S	Hebron Road	Major slide on lower side of the road with impacts to the roadway and stream below.
1414103 C	NCLP-HR#4S	Hebron Road	Major slide on lower side of the road with impacts to the roadway and stream below.
1504089 C	NCLP-HR#5S	Hebron Road	Minor slide on the lower side of the road with impacts to the roadway and utilities.
1504087 C	NCLP-HR#3C	Hebron Road	Culvert damaged due to slide area. Culvert will have to be replaced.
1414100 C	NCLP-HR#1S	Hebron Road	Slide area on lower side of Hebron Road above the Poplar Lodge that has impacted the shoulder and will impact the roadway.
Project - Primary Road Areas (Project Number 803291)			
1414104 C	NCLP-RD#1S	Roberts Drive	Major slide at the intersection of Roberts Drive and Rowland Drive below the road with impacts to the road and utilities.
1414109 C	NCLP-LPH#2S	Laurel Park Highway	Major slide both above and below the road affecting the ditch line and culvert with possible impact to the road.
Project - Davis Mountain Road Area (Project Number 799634) - NCDOT Project			
1414099 C	NCLP-DM#1S	Davis Mountain Road	Slide area on the lower side of Davis Mountain Road that has impacted the road way and damaged homes below.
1509828 C	NCLP-DM#2S	Davis Mountain Road	Just west of the DM#1S area, a portion of Davis Mountain Road has begun to settle. A large transverse crack has been observed.
1414121 C	NCLP-DM#2C	Davis Mountain Road	Culvert between Azalea Ridge Road and Country Ridge has washed out affecting the road and utilities. Culvert will have to be replaced and the road repaired.
Project - Fairway Drive Area (Project Number 951716)			
1414091 C	NCLP-FD#1S	Fairway Drive	Major slide with impact to roadway and impact to golf course below.
1414092 C	NCLP-FD#2S	Fairway Drive	Major slide with possible impact to roadway shoulder and roadway.
1414093 C	NCLP-FD#3S	Fairway Drive	Major slide with impact to roadway and impact to property below.
1414094 C	NCLP-PD#1S	Panaroma Drive	Major slide with impact to gravel road and impact to property below.
Project - Sunny Ridge (Project Number 816622)			
1414105 C	NCLP-SR#1S	Sunny Ridge Road	Slide affecting the road and blocking a culvert creating an impoundment of water. Culvert will likely have to be replaced.
1504093 C	NCLP-SR#1C	Sunny Ridge Road	Culvert blocked due to slide area. Culvert will likely have to be replaced.
Project - Old Laurel Drive Area & Orchard Circle/Tower Circle Area			
1414096 C	NCLP-OLD#1S	Old Laurel Drive	Major slide with washout of retaining wall with impact to upper and lower roadway. Retaining wall will be required based on limited area between roads.
1414097 C	NCLP-OLD#2S	Old Laurel Drive	Slide area on the upper side of Old Laurel Drive that has impacted drainage swale and culverts. Material must be removed from ditches, shoulder and roadway.
1504061 C	NCLP-OLD#1C	Old Laurel Drive	Culvert and roadway partially washed out. Culvert will have to be replaced and road repaired.
1414098 C	NCLP-WD#1S	Westwood Drive	Major side with impact to roadway and stream below.
1414106 C	NCLP-OC#1S	Orchard Circle	Slide affecting the road and blocking a culvert creating an impoundment of water. Culvert will likely have to be replaced.
1414107 C	NCLP-OC#2S	Orchard Circle	Slide above the road that has blocked a culvert and affected the road

1414115 C	NCLP-TC#1S	Tower Circle	Slide and evidence of slope instability on Tower Circle between Orchard Circle and Toms Drive.
1516457 C	NCLP-OC#1C	Orchard Circle	Culvert blocked due to slide area. Culvert will have to be cleaned out and assessed for replacement.
Stand Alone Projects			
1414112 C	NCLP-WH#1S	Winter Holly Lane	Major slide affecting the roadway and utilities.
Possible Small Projects			
1509835 C	NCLP-OC#1PD	Orchard Circle	Pavement damage from fallen trees.
1509836 C	NCLP-PD#1PD	Panorama Drive	Pavement damage from fallen trees.
1509837 C	NCLP-PD#2PD	Panorama Drive	Pavement damage from fallen trees.
1414114 C	NCLP-WL#1WO	Woodbyne Lane	Major washout of the gravel road affecting shoulders, road surface, etc.
1546857	NCLP-DM#3S	Davis Mountain Road	Pavement and curbing damaged
1509856 C	NCLP-OCL#1C	Old Creek Lane	Pavement has settled around an existing inlet. Storm drainage inlet and pavement will have to be repaired.

Potential NCDOT Managed Project